

EXHIBIT "A" - PHOTOS



TYPICAL UNIT



TYPICAL UNIT WITH SCREEN ENCLOSURE

EXHIBIT "A" - PHOTOS



TYPICAL UNIT WITH COVERED FLAT SCREEN ENCLOSURE



BALCONY SLAB EDGE SPALL WITH EXPOSED REBAR

EXHIBIT "A" - PHOTOS



BALCONY SLAB EDGE SPALL



BALCONY CEILING SLAB SPALL

EXHIBIT "A" - PHOTOS



BALCONY CEILING SLAB SPALL




BALCONY SLAB SPALL NEAR SLIDING GLASS DOOR

EXHIBIT "A" - PHOTOS



BALCONY SLAB SPALLS AND EXPOSED REBAR



SLAB SPALL NEAR SLIDING GLASS DOOR

EXHIBIT "A" - PHOTOS



SPALL BETWEEN SHUTTER TRACK AND SLIDING GLASS DOOR



SPALL UNDER SHUTTER TRACK

EXHIBIT "A" - PHOTOS



SLAB EDGE SPALL AND VEGETATION



BALCONY SLAB EDGE SPALL AND EXPOSED RAILING BOLT

EXHIBIT "A" - PHOTOS



BALCONY SLAB SPALL NEAR RAILING BOLT




EXPOSED REBAR ON BALCONY

EXHIBIT "A" - PHOTOS




EXPOSED REBAR ON BALCONY



EXPOSED REBAR ON BALCONY

EXHIBIT "A" - PHOTOS



EXPOSED REBAR ON BALCONY




SLAB SPALL AND EXPOSED CHAIR TIPS

EXHIBIT "A" - PHOTOS



WALL SPALL



WALL SPALL WITH EXPOSED REBAR

EXHIBIT "A" - PHOTOS



WALL SPALL WITH EXPOSED REBAR



BEAM SPALL

EXHIBIT "A" - PHOTOS



BEAM SPALL



BEAM SPALL

EXHIBIT "A" - PHOTOS



SLAB SPALLS AND CUT/MISSING RAILING, AND BOLT



RUSTED BALCONY RAILING BOLTS

EXHIBIT "A" - PHOTOS



MISSING BALCONY RAILING BOLT



RUSTED AND MISSING BALCONY RAILING FASTENERS

EXHIBIT "A" - PHOTOS



RUSTED / DETERIORATED RAILING POST FASTENER



CEILING SPALL UNDER RAILING BOLT, UNUSED FASTENER HOLE

EXHIBIT "A" - PHOTOS



VISIBAL RUSTED REBAR AT BALCONY EDGE



RUST SPOT AT BALCONY SLAB EDGE

EXHIBIT "A" - PHOTOS



CRACKED AND LIFTED TILE, VEGETATION




INTERIOR WATER DAMAGE / POSSIBLE SPALL NEAR SGD

EXHIBIT "A" - PHOTOS



SLAB SPALLS AND UNUSED FASTENERS ON BALCONY SLAB



REFERENCE